

Swan Hill Sporting Car Club

Working Bee Projects

5: Fix or replace sprinkler sockets leaking at the back of club house and in middle of track

There is a water leak in the centre of the 2 tracks where a nice green patch is near where the old start line was in front of the clubhouse very easy to see.

It is a sprinkler socket

The water is supplied via the main line to the club house and is isolated at the pump ball valve with the blue handle at the water tank outside the toilet block.

Identify what is causing the water leak and replace parts there are many fittings for this pipe in the 20' shipping container.

There is another problem at the back of the club house under the veranda and has a tire over the location it leaks from time to time and it too is a sprinkler socket.

Materials should be in site in 20' shipping container

Time 1 or 2

2 people would make it easier.